



22 Defective gutter south side of garage



23 North east chimney, cracked render & defective pointing under cope



26 Front window bay, cracked render (typical)



27 Front dormer, defective pointing under cill



24 North west chimney, defective brick pointing & can



25 South west chimney (rear of photo), defective brick pointing